

SP – 210 Tin and Solder Addition Agent

DESCRIPTION

SP-201 is a ready to use liquid stabilized organic grain refiner. It is a non-peptone based addition agent used in electroplating tin and solder alloys. SP-201 has been formulated to improve the throwing power of the bath, aid in refining grain structure, and prevent treeing. Added on a routine basis, it will increase limiting current density and control deposit ratio. Its bright silver white deposit gives a re-flowable alloy over a wide range of current densities.

OPERATING PARAMETERS

SP201 components	See the make-up section below
Temperature	70 to 85F (21 to 30C)
Immersion Time	Depends upon thickness desired
Current Density	10 to 40 Amps/Sz. Ft. 1.1 to 4.3 Amps/Sq. D
Anodes	Baskets or Slab, 63 Tin / 37 Lead
Anode Bags	Plypropylene or Dynel
Filtration	Continuous while plating
Ventilation	Advised
Tanks	Polypropylene, Polyethylene, PVC
Racks/Baskets	Stainless Steel, Plastisol Covered Steel
Heaters	Stainless Steel, Teflon Coils

CHEMICAL PARAMETERS

Stannous Tin Metal	3.0 to 3.5 ozs per gallon (22 – 26 g/L)
Lead Metal	1.8 to 2.1 ozs per gallon (13 – 16 g/L)
Tin to Lead Ratio	1.6 to 1.8 : 1
Fluoboric Acid 50%	12.0 to 18.0 oz per gallon (9 – 14% by volume)
SP-201CS	1.5 oz. per gallon (11.5 g/L)
SP201M Addition	4.0% by volume on make-up
SP-201 Addition	0.38 mls per amp hour

PHYSICAL PROPERTIES

	SP 201 M	SP 201	SP 201C
Specific gravity	1.00-1.04	0.98-1.02	NA
Appearance	Dark brown liquid	Brown liquid	Crystal blend
pH	9.0-10.0	9.0-10.0	NA
Odor	Surfactant	Surfactant	None
Flash Point	>200F	>200F	>200F

CONTROL PROCEDURES

NEW BATH START-UP PROCEDURES

Prior to bath make-up, the tank must be clean and leached with a 5% solution of Fluoboric Acid for a period of 12 hours. The anode bags should be washed in warm water to remove any sizing and then leached in 5% solution of fluoboric acid. All equipment, heaters, filters, racks, etc., should also be washed prior to coming in contact with the new plating solution.

NEW BATH MAKE-UP

BATH	PER 100 GALLONS	PER 100 LITERS
50.0% Stannous Fluoborate	7.5 Gallons	7.5 Liters
50.0% Lead Fluoborate	3.5 Gallons	3.5 Liters
50.0% Fluoboric Acid	10.5 Gallons	10.5 Liters
SP-201CS	9.0 Pounds	1.1 Kilograms
SP-201M	4.0 gallons	4.0 Liters

MAKE-UP

1. Fill tank half way with de-ionized water.
2. Add the required amount of Fluoboric Acid and mix.
3. Add the required amount of lead fluoborate solution and mix.
4. Add the required amount of stannous fluoborate and mix.
5. Add the required amount of SP-201CS and mix until dissolved.
6. Add the required amount of SP-201M addition agent and mix.
7. Raise the volume of the bath to operating height with de-ionized water.
8. Fill a clean anode bag with boric acid and place it in the corner of the plating tank.
9. The plating solution is now ready to use.

SOLUTION CONVERSIONS

Peptone and non-peptone plating baths can be converted to SP-201 plating bath. A simple batch carbon treatment will remove the organic addition agents. This can be accomplished by treating the bath with 4 pounds of carbon per 100 gallons. Carbon treatment can also be accomplished by continuously filtering the bath through activated carbon filters until a 2-amp 5-minute hull cell shows no sign of active grain refiner. After the organics have been stripped out of solution, and alloy ratio adjustments have been made, the addition agent can be added and plating can continue.

RATE OF DESPOSITION FROM SOLDER BATH

AMPS/SQ FT mils	.0001	.0002	.0005	.001
10	4.5 min.	9.0 min	22.5 min	45.0 min
20	2.3 min	4.5 min	11.3 min	22.5 min
30	1.5 min	3.0 min	7.5 min	15.0 min
40	1.1 min	2.2 min	5.6 min	11.2 min

AMPS/SQ D microns	2.54	5.08	19.7	39.4
1.4	3.0 min	6.0 min	15.0 min	30.0 min
1.87	2.3 min	4.5 min	11.2 min	22.5 min
2.8	1.5 min	3.0 min	7.5 min	15.0 min
3.73	1.1 min	2.2 min	5.6 min	11.2 min

ANALYSIS

DETERMINATION OF STANNOUS TIN

1. Pipet 2.0 mL of the working bath into a 250 mL Erlenmeyer flask.
2. Add 75 mL of DI water and 25 mL of 50% v/v HCl.
3. Add about 0.2 g of sodium bicarbonate slowly with mixing.
4. Add 5 mL of starch indicator solution.
5. Titrate with 0.1 N Potassium Iodate - Iodide to the blue/black endpoint.
6. Calculation:

$$(\text{mls. of 0.1N Iodate-Iodide}) \times 0.5 = \text{Stannous Tin (oz/gal)}$$

To raise the tin content 0.1 ounces per gallon add 0.24 gallons of Stannous Fluoborate 50% concentrate per 100 gallons.

DETERMINATION OF FLUORBORIC ACID

1. Pipette 5.0 ml of the plating bath into a 250-ml Erlenmeyer Flask.
2. Add 5 mls of 13.5% Sodium sulfate (wt/vol.) solution and ~50 mL of DI water and mix.
3. Add 2-3 drops of methyl orange – xylene cyanole indicator.
4. Titrate with 1.0 N NaOH to a gray end point.
5. Calculations:

$$\text{Free Fluoboric acid (oz/gal)} = (\text{mls. NaOH} \times \text{N NaOH}) - (0.1714 \times \text{Sn}^{++} \text{ oz/gal}) \times 2.12$$

Alternate Calculations:

$$(\text{mls. of Sodium Hydroxide}) \times 1.8 = \text{ounces per gallon of Total Fluoboric Acid}$$

$$(\text{mls. of Sodium Hydroxide}) \times 19.7 = \text{mls per liter of Total Fluoboric Acid}$$

To raise the fluoboric Acid content 1.0 ounces per gallon add 1.12 gallons of 50% fluoboric Acid per 100 gallons.

DETERMINATION OF LEAD

1. Pipet a 2 mL sample into a 250 mL titration flask and dilute to 100 mL with DI water.
2. Add 3-4 drops of 50% hydrogen peroxide and shake. Let stand 5 minutes.
3. Add exactly 5 mL of 0.05 M EDTA solution and mix well.
4. Add 5 mL of 20% triethanolamine solution and 10 mL of ammonium buffer and mix well (Buffer: 54g/L ammonium chloride and 350 ml/L ammonium hydroxide)
5. Add Eriochrome Black T indicator to get a blue color.
6. Titrate with 0.01 M zinc nitrate until the color changes to violet.
7. Calculation

Lead (oz/gal) = (25 – mL of zinc nitrate) x 0.138

To raise the lead content 0.1 ounces per gallon add 0.15 gallons of Lead Fluoborate 50% concentrate per 100 gallons of plating solution.

SAFETY AND STORAGE

SP-201 is a slightly irritating solution. It contains wetting agents and organic surface conditioners. Avoid breathing vapors. Use in a well-ventilated area. When handling concentrate or working solution, wear protective clothing, gloves and chemical safety goggles. In case of skin contact, remove contaminated clothing and flush affected area with plenty of cold water. In case of eye contact, flush immediately with plenty of cold water and seek medical attention immediately.

Store SP-201 in its original container. Keep away from direct sunlight and temperature extremes. Protect from freezing.

WASTE TREATMENT

SP-201 contains organic wetting agents and surfactants. Discarded solution can be treated by adjusting the pH to between 6 and 8 before sending the spent solution to the sewer. Consult with local officials for further waste disposal regulations. Please ask a Florida CirTech sales rep. for more information regarding waste treatment of this chemistry and our complete line of waste treatment chemistry if additional help or information is desired.

MISCELLANEOUS

Available in 5-gallon pails and 55 gallon drums. Consult MSDS for additional information.

TROUBLESHOOTING GUIDE

PROBLEM	CAUSE	CORRECTION
Treeing	Low SP-130 Low Sulfuric Acid Low Temperature	Add SP-130 to required levels Analyze and adjust acid content Adjust to within operation limits
Roughness	Stannic tin or solids in bath	Filter solution
Graininess	Low SP-130 Tin content too low	Add SP-130 to required levels Add Stannous Sulfate
Dark Plating Bath	Low temperature Low SP-130	Adjust temperature Add SP-130 to required levels
Burning	Low temperature Too high current density	Adjust temperature Lower current
Blistering	Poor surface Cleaning	Check and adjust pre-cleaning
Streaking	Low SP-130	Add SP-130 to required levels
Reduced Throwing Power	Low SP-130 Low Sulfuric acid Low tin content	Add SP-130 to required levels Analyze and adjust acid content Analyze and adjust
Gassing	Too high a current	Lower current density
Polarized Anodes	Anode current density too high	Add anodes or lower current density
Brittle deposits	Organic contamination	Carbon treat